

Surveyor 3.5.98

Received from Chief Surveyor

NAME S.S. Strathleven

Report Ips. No.

For the CHIEF SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

No. ~~SURVEY PARTLY HELD.~~

When proposed to be completed

By held, &c.

Vessel left Harwich 12 March for Norfolk U.
Arrived at Dunkirk 26 April.

It is submitted the Ipswich Surveyor be informed that no repairs of this vessel has yet been received at this Office. It should be pointed out to him that he was requested in the letter addressed to him on the 16th. March to advise the Secretary immediately to what port the Vessel would proceed, and ^{his} having omitted to do so has caused inconvenience.

The case should be referred to the Glasgow Surveyors and they be requested to ascertain, whether the damage in question has been repaired and when and at what port it will be convenient for the vessel to be inspected by one of the Society's Surveyors.

W. Hill & note
+ write Ips & Gls. 4/5/98.
Ips }
Gls } 4/5/98.

C. A. J.
4/5/98

