

7. 398

Received from Chief Surveyor

Shamleven

Report

Ips

No.

2698

For the CHIEF SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

It is submitted that before this case receives the consideration of the Committee, the Ipswich Surveyor should be requested to state whether the necessary repairs to this vessel are to be carried out at his port, and if not at what port they will be effected. If the repairs are to be done at his port, he should forward a report on the usual report form for the information of the Committee in the usual completion of the repairs.

J.H.T.
8/3/98.

C.A.P.

Ips: 8/3/98



© 2018

Lloyd's Register
Foundation