

ived by Chief Surveyor

16-1-00

Received from Chief Surveyor

SEL'S NAME

Lion S. S. Strathleven

Report

Two

No. 39469

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

DAMAGE.

ure of Survey

Damage through

collision

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	/						
Removed and faired or repaired.....							
Faired or repaired in place.....	/						

Other items:-

On account of wear & tear some minor repairs have been effected.

A new bow anchor of sufficient weight & properly tested has now been supplied to replace one broken.

It is submitted the vessel is worthy to remain classed

100 A1

with

record of Survey 1, 00

as recommended.

100 A1

1, 00 Two

C. H. J.

16/1/00



© 2018

Lloyd's Register
Foundation