

Port of GRIMSBY.

MAY 26 1943.

REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined
Masts, Spars, and Rigging, and Iron Work of same, of the
LIZZIE & ANNIE

have to report that I found the Fore Stay and six main
Rigging Shrouds well rusted at the lower ends
but the wire in fair condition.

The Stay and Rigging stretching screws and
ratchets require releasing and made workable
topping left. Wire good on main Derrick.
Lower ends of the Fore Stay and Main Shrouds
require cleaning greasing & re-serving for not
less than six feet.

A. F. Jones.

£ - . 10 : 6

the Surveyors,
Lloyd's Register of Shipping,

Grimby.



© 2018

Lloyd's Register
Foundation