

BOARD REPORT on the

Lizzie & Annie

It is submitted the report form No 8 should be returned to the Surveyors who should be requested to complete the same by stating in detail particulars regarding the extent of the internal survey now held.

The Surveyors should also be requested to check the sheers given on their 11a report form in view of the discrepancy between the sheers reported on Hull report No 16102 in July 1964 which were as follows: Stem 26", Sternpost 17½", ¼ from Stem 13", ¼ from Sternpost 10". also the round of beam now given as 5" instead of 6" as formerly.

Per Ldrl 12/11/13.

GRM

MD

12-11-13



© 2018

Lloyd's Register
Foundation