

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 22567 Date of Writing Report 23rd Mar 1889 Port of Newcastle
 No. in Reg. Book. Survey held at South Shields Date, first Survey and Last Survey 21st Mar 1889
 21 on the Machinery of the S. S. Bakuin Master No. of Visits 1
 Tonnage Gross 1669 Net 1095 Vessel built at W. Haslip By whom W. Gray & Co. When 1886
 Registered Horse Power 200 Engines made at W. Haslip When 1886 Boilers, when made (Main) 1886 (Donkey) -
 No. of Main Boilers Owners A. Stuart Port London Voyage
 Steam Pressure in Main Boilers 150 If Surveyed Afloat or in Dry Dock Middle Dock Class of Vessel & Machinery 100A1 12.7
 in Donkey Boiler (State name of Dock.) (as in Register Book.) + 1. M. 6. 8. 16

Last Survey No. Port
 Particulars of Examination and Repairs (if any) Sighting Bottom
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from
 Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? No
 If this was not done, state for what reasons?
 And what parts of the Boilers could not be thus thoroughly examined?
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Sighted Bottom propeller and sea cock fastenings good.

General Observations, Opinion, and Recommendation:—The machinery of this vessel
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey.)
 as far as seen is in good and safe working condition and
 eligible in my opinion to remain as classed in the Register
 Book

Office or Registration Fee (per Sec. 27).....	£ : : : :	Fees applied for
Survey Fee (per Section 25).....	£ : : : :	188
Special Damage, Fee (per Section 25).....	£ : : : :	
*Certificate (if required) as per margin.....	£ : : : :	Received by me,
Travelling Expenses (if chargeable).....	£ : : : :	188

Jas Barclay
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRIDAY 29 MARCH 1889

Assigned Remain as classed

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

CONDITION OF THE		REPORT OF THE	
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92
93	94	95	96
97	98	99	100

It is submitted that this
need is eligible to
remain as
Classed
17d.
27 304

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

LR-FAT-3416-32