

S. S. Bakwin

Spl. Rept. No. 8234

As the patent Enamel (Dag's) which  
was found blistered & worn off in places  
was repaired with Portland Cement, it is  
submitted that an early opportunity should  
be afforded to re-examine the Ballast  
Tank internally, in order to ascertain  
whether the Portland Cement has properly  
adhered to the several surfaces & whether any  
increase is to be found in the extent of the  
blistering & wear already reported.



© 2018  
Lloyd's Register  
Foundation 242