

Chief Surveyor 12/12/95

Received from Chief Surveyor _____

L'S NAME Ste. S.S. Baku Standard Report Phl. No. 676

remarks of the Chief Sarveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

GROUNDING.

of Survey _____

This vessel is reported by the Philadelphia Surveyor to have been examined as far as practicable afloat, after grounding, and so far as could be seen no injury appears to have been sustained. The Surveyor however recommends that she should be examined in dry dock at the first convenient opportunity

It is submitted the Owners should be informed accordingly, and asked to state when, and at what port, it will be convenient for this to be done. In the meantime the Class might be allowed to remain undisturbed.



E. J. M.
© 2018
12/12/95
Lloyd's Register
Foundation