

Received by Chief Ship Surveyor 10.9.03.

Received from Chief Ship Surveyor _____

VESSEL'S NAME S.S. Baku Standard Report Phl No. 1191

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

DAMAGE.

Nature of Survey _____

Damage through Ice

B.S. due 7.03.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	8	23	21	6			
Removed and faired or repaired.....	8			3	2		
Faired or repaired in place.....	5			10			

Other items:-

Bilge stringer renewed in fore peak,
collision bulkhead repaired, cement + ceiling
repaired minor repairs.

wear steer:- Some rivets renewed in fore
peak.

It is submitted the vessel is worthy to remain as classed with
record of Survey 8.03 as recommended.

10001 spar &c
Carrying pet. in bulk.
8.03 Phl.

