

Received by Chief Ship Surveyor

7/4/05

Received from Chief Ship Surveyor

VESSEL'S NAME

S.S. Bark Standard

Report No.

48601

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage S.S. No 3 due 2-05

This vessel has been examined in dry dock, bottom cleaned and coated and some damage through ice has been temporarily repaired. The Owners Superintendent informed the Surveyors that permanent repairs would be effected when the S.S.No.3 which became due in February last is held, and which it is proposed to carry out in the Autumn.

It is submitted this proposal might be approved and the vessel allowed to remain as classed without record of survey as recommended.



© 2018

Lloyd's Register
Foundation