

Rpt. 8.

(Received at London Office)

THUR. FEB 14 1907

No. 52359

REPORT of SURVEY for REPAIRS, &c.

Date of writing report

1. Feb 10. 07 when handed in at Local Office

1. Feb 10. 07 Port of

Newcastle

No. in Reg. Book.

Survey held at Birth Slipper Date, First Survey 25 June Last Survey 25 January 1907
on the Wood, Tyneside S.S. BAKU STANDARD (No. of Visits)

Built at Newcastle By whom W. G. Armstrong, Mitchell When 1893 Master Stewart

Owners I Clark & Sons Port belonging to London

Owners' Address

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Smith & Sons Destined Voyage Port Arthur, Ta.

WB=Cell D Borr DBa feet; ue&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount & deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler spaces.

Last Report, No. 51001 Port New.

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER
For Special Survey,
Date of last Survey and of
Periodical SurveysMachinery and Boiler
Surveys
(including date of N.R., if any).Anchored
Aground
Stranded

+100 ft. 1. +100 ft. 1. +100 ft. 1.

Jan 1st 5.06 Jan 1st 5.06 Jan 1st 5.06

Repairing Bottom in Bulk
S.S. Ship No 35-06

Society's Freeboard (if assigned) as painted on Ship and now verified

ft. in.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking Survey.

Vessel placed in dry dock bottom & main examined. A few rivets in fore peak renewed. Rusty light fragum rubbed. Bottom cleaned and riveted.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Paired or Repaired								
Paired or Renewed in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or V.M. of Wood Vessels
Decks	/	/	Paint
Caulking of Decks	"	/	(State if on Felt.)
Waterways	"	/	When put on, Month Year
Coamings	"	/	Boats
Beams & Fastenings	"	/	Masts, Yards, &c.
Outside Plating	/	/	Condition, how ascertained
Caulking of ditto	"	/	(State if wedges removed)
Rivets	"	/	Walls
Breasthooks & Crutches	/	/	Equipment letter
Transoms	/	/	Anchors, No. of 313150K
Frames	/	/	Cables (State if now ranged)
Reverse Frames	/	/	" length reported
Floors	/	/	" (on board) Compsub-
Keelsons	/	/	" Rule length (per Table 22)
			Hawsers & Warps
			Duffin-
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-05," or "to remain as classed and to have record of survey, 1-05, and the notations of No. 1-05 and PND 05, &c."

This vessel is in apparent good & efficient condition. Suitable in my opinion to continue as classed with fresh record of survey 1-07.

Survey Fee (per Section 28)	£	1	Fees applied for,	
Special Damages or Repair Fee (if any) (per Sec. 28)	£	1	Received by me,	10
Travelling Expenses (if chargeable)	£	1		10
Second Surveyor's Fee (if any)	£	1		

Committee's Minute FRI. FEB 15 1907

Character Assigned 100A1

Carrying petroleum in bulk JGD