

Received by Chief Ship Surveyor

8/12/08

Received from Chief Ship Surveyor

VESSEL'S NAME

St S Baku Standard Rpt. Two

No. 55816

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

DAMAGE.

Damage through

heavy weather & grounding & ice
also tho' cause not known

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	1						
Faired or repaired in place.....	1	3					2

Other items:- a number of rivets missed, some
caulking made good, a bar anchor & 120
fathoms of chain cable of proper weight & eye
shot supplied & minor repairs.

Repairs due to wear & tear:- 8 casing plates
missed & minor repairs.

It is submitted the vessel is worthy to remain as classed with
record of Survey 11.08 as recommended.

100A1 Spar deck
Carrying petroleum in bulk
11.08 S.H.

R.B.A.
8/12/08
C. J. L.