

Received by Chief Ship Surveyor *24/2/09*

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *H. S. Bam Standard* Rpt. Off \_\_\_\_\_ No. *20386*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.\*—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey \_\_\_\_\_

Damage through *heavy weather & grounding*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	/						
Removed and faired or repaired.....							
Faired or repaired in place.....	/						

Other items:- *A number of rivets renewed, some caulking made good, several ropes supplied & minor repairs to deck fittings etc.*

*Bottom examined cleaned & treated*

It is submitted the vessel is worthy to remain as classed with record of Survey *2-09* as recommended.

*100A1 Spar deck  
Carrying futwolum in bulk  
2-09 Off*

*RPT  
24/2/09  
C.H.J.*