

The Surveyors should be requested to state whether, in their opinion, the owners proposal to carry out the Special Survey No 2 at the first convenient opportunity ^{with the go ahead} merits approval. They should also be requested to state what part if any of the examination detailed in their report No 14/62 may be taken as a portion of the Special Survey No 2

 
23.6.74

Received by Chief Ship Surveyor 15.6.14

Received from Chief Ship Surveyor 15 JUN 14

1

VESSEL'S NAME Steel S.S. "Baku Standard"

Rpt. Bry No. 14162

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/3/02.)

Nature of Survey

DAMAGE.

The 2nd S.S. No 2 became due 5.14.

Damage through grounding and heavy weather

(see Jan apt 1395'0
.. Feb - 5489)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	6	9 pt					
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- Vessel examined in dry dock - bottom cleared & coated. 6 tank side plates and 32 lugs renewed. 9 web frame plates renewed & bulwarks repaired as necessary. Repairs (wear & tear) 22 reverse frames partly renewed. 26 tank side brackets renewed. 4 engine room tank top plates renewed & 2 doubling plates fitted to boiler room tank top. 1 shell plate renewed. Bunkers, casings, screen bulkhead & fidley tip plates repaired. Minor repairs effected.

The Surveyor reports that the main piece of the rudder was found worn in way of 2nd, 3rd arms & recommends that this should be examined at the 2nd S.S. No 2. It is submitted the vessel is worthy to remain as classed with ~~action be deferred and the surveyor informed of the Surveyors~~ as recommended.

M. 22. 8. 14