

not in demised list

19 JUN 1917

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

18.6.17

Mss. Baku Standard

Report

hwc.

No. 68790

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/12.)

2nd No. 2

SURVEY PARTLY HELD.

574

When proposed to be completed

Moly Curvey held.

B.S. due 6.15 partly held.

on due

tion of Survey held, &c.,

The 2nd Special Survey No.2, which became due 5.14, has been partly held, and to complete same all Rule requirements to be complied with, except examination of the vessel in dry dock, internal examination & testing of Engine room tank, ranging of cables and examination of the rigging. A few bolts in after deck to be replaced by rivets. To complete the boiler survey, the donkey boiler requires to be surveyed in its entirety & the main & donkey funnels removed. Action has been deferred from time to time, the vessel being on Government service.

The case was last before the Committee on the 6th March, when action was deferred for the present.

The Owners now state, in reply to enquiry, the Vessel continues under Admiralty requisition, and her movements are therefore not under their control.

The case is therefore submitted for the consideration of the Committee.

19. 6. 17