

F.E.

Received by Chief Ship Surveyor 8.11.07

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. Quad. Screw Turbine S. Mauritania Rpt. Nve. No. 53784

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>As approved</u>	
Spar Sheerstrake . .		
Description of Framing:— <u>Channel, as approved.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \ddagger 100 A 1 ("Steel") as recommended.

\ddagger 100 A 1 ("Steel")

Deck (Stl) Skelton DR (Stl - ws) & lower ^{also} DR (Stl) in forward & after holds.

N. B = Cell DB a 46' in E 4 B 481' f 125' 4389t DT f 44' 546t FPT 202t APT 53t

FK 11BH Asp. Lloyd's 14CP Cromwell DR 452' Boat DR 584' F 305'

C.H. J.
8/11/07