

COPY.

Lloyd's Register of Shipping.



Port SOUTHAMPTON.

10th July, 1934.

This is to Certify that

J. McILLAN.

the undersigned Surveyor to this Society did at the request of
owner's representative survey Q.S.S. "MAURETANIA", 30696 tons
gross of LIVERPOOL on 30th April, 1934 and subsequently whilst
the vessel lay afloat at Southampton for the purpose of
ascertaining and reporting upon the nature and extent of damage
stated to have been sustained through intense frost whilst
approaching New York from a cruise, Voyage No. 306.
For further particulars see log books.

The undersigned upon examination

FOUND:-

Paintwork cracked and loosened
from steel work, large areas
broken and cracked on Bridge
Deckhouse, Games deck, Vents,
and funnels, Boat Deckhouse,
1st Class and Tourist, Boats,
"B" Deckhouse 1st Class and
Tourist, "B" Deck bulwarks and
deckheads, "C" Deckhouse.
Painted wood on Sun Deck 1st
class and Tourist cracked and

RECOMMENDED:-

All loose and broken paintwork
on deck houses to be removed,
and deckhouses sealed smooth
cemented and painted two coats
lead and 1 coat flat and one
coat enamel.
All loose paintwork on Deck-
heads, Bulwarks, vents etc., to
be removed, surfaces sealed
smooth and painted 1 coat red
lead, 1 coat lead, 1 coat flat.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
publication of the Society, or for any error of judgment, default, or negligence of the Committee or any member thereof, or
Surveyors, or other Officers or Agents of the Society."

10th July, 1934.

"MAURITANIA".

Voyage No. 406.

FOUND:-

and broken.

RECOMMENDED:-

and 1 coat glass white. All
loose paint on wood deck to
be scraped off and 1 coat
applied.

The above recommendations have been carried out to the
satisfaction of the undersigned.

Damage & Repair Fee:- £1.-1.-0.

Mention

SURVEYOR TOLLOID'S REGISTER OF SHIPPING.



© 2018

Lloyd's Register
Foundation