

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

191 When handed in at Local Office

191

Port of London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

191

60

on the ~~Wood, Iron or~~ Steel ⁴ Mst Bk. "Passat"

(No. of Visits)

Master J. Wendler 07-11

YEAR

MONTH

TONNAGE:—

GROSS 3091

UNDER DK. 2850

NET 2882

Built at Hamburg

By whom Blohm & Voss

When 1911

11

Owners J. Laciog

Port belonging to Hamburg

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet: uE&B

feet: f

feet: }

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons. }

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides
of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,
girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 13899 Port

Ham

100A/ 2,14

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the
cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs
on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes;
and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on
the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as
painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why
they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

Renewed ...
Removed and Paired or Repaired ...
Paired or Repaired in place ...

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found effi-

cient?

Have Sluice Valves now been examined and found

efficient?

Have Watertight Doors now been examined and found

efficient?

Dbing. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treemills

Breasthooks & Stemson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelves ditto

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Felt.)

When put on, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if redges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

.. length size

(on board)

.. Rule length size

Hawser & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned



© 2018

Lloyd's Register
Foundation

[illegible]

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Iron Stream Chain
or Steel Wire...

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.