

Port of H A M B U R G

16th of February 19 26.

## REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined  
the Masts, Spars, and Rigging, and Iron Work of same, of the  
Steel 4 Mst.Bk. " P A S S A T " 3091 Tons of H A M B U R G

I have to report that I found Foremast:

the cleading of the fore-topgallant-stay in way of block on the  
jib-boom badly pressed.-On the fore-side of the Topsail-halliard  
Sheave some rivets loose.---

Main-mast; Nothing!

Mizzen-mast:

Mizzen Royal-yard on port arm repaired by a strap.

Jigger-mast: Nothing!

Carl Krepcke.

KOEPCKE, REITZ & KIPP  
Schiffstaklerei

Fee £ Mk: 25.-

To the Surveyors,  
Lloyd's Register of Shipping,

