



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Hamburg 1, Ballindamm 25

Telephone: No. 33 10 25

23rd May, 1956

Telegrams: Surveyors, Hamburg

Reference:  
sn(S).

Dear Sir,

"PASSAT"  
Hamburg Report No. 4665

Reference your classing letter of 11th instant on the above subject informing us that the ship's class was made subject to 'propulsion motor supercharger clutch to be overhauled and examined on ship's arrival from present voyage at a European Port' we have to state that no examination was carried out on this subject. We would like to mention that no certificate was available on board, nor was this item in the S.R.L. No. 141.

Yours faithfully,  
The Surveyors.

Per:

*J. H. Clugston*

The Secretary,  
London.



© 2018

Lloyd's Register  
Foundation

LLOYD'S REGISTER OF SHIPPING  
UNITED WITH THE BRITISH CORPORATION REGISTER

Hamburg 1, Ballindamm 25

Telephone: No. 33 10 23

23rd May, 1952

Telephone: 244400, Hamburg

Dear Sir,

"PASSAT"  
Hamburg Report No. 4669

Reference your classing letter of 11th instant on the above subject informing us that the ship's class was made subject to 'propulsion motor supercharger clutch to be overhauled and examined on ship's arrival from present voyage at a specified port' we have to state that no examination was carried out on this subject. We would like to state that no certificate was available on board, this item in the S.R.L. No. 141.

*[Handwritten signature in blue ink]*

Per:

The Secretary,  
London

© 2018  
Lloyd's Register  
Foundation



LR-FAF-5A27-290

CLASSIFICATION

*[Handwritten initials]*

*[Handwritten signature]*

H

*[Handwritten notes in blue ink, slanted across the page]*

①  
4/4

