

Lloyd's Surveyors Office,  
Hull <sup>10</sup> Nov<sup>r</sup> 1866

Sir

I have to acknowledge the receipt of your letter of the 6<sup>th</sup> inst. Relating to reports as per Nos. now quoted, No 3696. "Annie" This vessel was placed under Special Survey 25<sup>th</sup> March 1864 and the Certificate of Anchors & chain dated 1<sup>st</sup> June 1864. about which time the vessel was completed & the stores supplied. Under the above circumstances I will feel obliged by being informed what anchors I must request the Owners to replace -

No 3698. "Adler" The plating when drilled was the same as the original by  $\frac{11}{16}$ .  $\frac{11}{16}$  &  $\frac{11}{16}$  -

Yours Obed<sup>t</sup> Servant  
on 250 tons  
Scale

Wm. The Cert<sup>y</sup> of March  
for the "Acorn" rec<sup>d</sup>.  
with this letter  
G. B. Bayly Esq  
London



Lloyd's Register  
Foundation



Supp 14 "Arrive" The Suptent  
Cert<sup>o</sup> No 120 for 210 La. of  
Chain, 120-130 & 131 for  
Anchors; dated Jan 10 61  
and Signed Justice Wright &c  
returned to Hull Lawyers  
12/11/66