

Sent to Chief Surveyor

19.2.94

Received from Chief Surveyor

VESSEL'S NAME Iron S.S. "Stettin"

Report 1st No. 7431

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

S.S. No. 1 + Damage

On account of damage by fire :- upper and lower decks partly renewed : wood bulkhead at after end of forecastle renewed with iron : forecastle deck renewed : 12 forecastle beams and 4 stringer plates and pillars to forecastle beams faired and re-fitted, and foremast renewed : The requirements of the S.S. No. 1, due 12.93, have now been complied with.

The Surveyor states that the record of deck erections in the Register Book should be amended to "P 92' and F 105'".

It is submitted the vessel appears worthy to remain classed A/ with record of survey 2.94, and notation of S.S.Lth.No.1 -94, as recommended.

A/
2.94
S.S. Lth. No. 1 - 94

J. S.

WLG
19.2.94

Record of deck erections to be
amended to P. 92' F 105'

File B 50' for W.H.G.