

Sent to Chief Ship Surveyor 24.4.14

Received from Chief Ship Surveyor

VESSEL'S NAME Iron S.S. "Stettin"

Rot. hwe. No. 40069.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement so contains a succinct summary of any repairs that have been required and to show the name or names of such repairer, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24.5.92.)

Nature of Survey

DAMAGE.

This vessel is reported by the Newcastle Surveyors to have sustained damage to stem, stem plating, frames etc through striking Quay wall. Temporary repairs have been effected to ^a her satisfaction to enable her to proceed on her voyage. ☐

The Surveyor recommends that permanent repairs should be effected on return from the present voyage.

It is submitted the vessel appears worthy to remain as classed without record of survey subject as above, as recommended.
The Owners should be informed accordingly.

as now subjected.



© 2018

Lloyd's Register
Foundation