

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

1 - FEB 1928

VESSEL'S NAME Iron Sc."STETTIN".

Rpt. Nam.

No. 17858.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the name or names of each repairer, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/21.)

Nature of Survey.

The class is subject to the chart-house being repaired at the Owners' earliest convenience.

The Hamburg Surveyors now report that temporary repairs have been effected in way of damage sustained to stem plating etc., through collision and recommend that permanent repairs be carried out on vessel's arrival at Leith.

It is submitted action be deferred pending the receipt of a report from the Leith Surveyors who have been advised.




© 2018  
Lloyd's Register  
Foundation