

Received by Chief Ship Surveyor

30 MAR 1928
Received from Chief Ship Surveyor

VESSEL'S NAME Iron D.S. "STAMPIN".

Rpt. Dun.

No. 8038.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a concise summary of any repairs that have been required and to show the name or names of each repairer, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 745/VI.)

Nature of Survey

The Dundee Surveyor reports that a shell plate on port bow which was found fractured and holed through striking a buoy, has been doubled, but recommends that the plate be further dealt with at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed, without record of survey, subject as recommended.

As now. Subject to



© 2018
Lloyd's Register
Foundation