

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 845 No. 1301 Survey held at LONDON Date, first Survey 19th Apr Last Survey 29th Apr 1873.
 on the Iron S.S. 'Charles Howard' Master Ayles
 Tonnage 1021 built at Sunderland When built 1866 by Thos. Lee & Co.
 By whom built Pile Owners Rye & Co.
 Port belonging to LONDON Destined Voyage Marseilles
 If Surveyed Afloat & in Dry Dock Millwall Docks & Millwall Dry Dock
 Last Survey, No. 2074 Port LONDON Classed 90 St 1

REPAIRS, &c. Ironwork Placed on Blocks. Bottom cleaned & running decked.
and coated with Peacock's Patent Paint;

Present Condition of the

Decks	<u>Good</u>	Trunnels	<u>Paints</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		Pumps	
Comings	"	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	<u>Good</u>	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	<u>where seen</u>	Condition, how ascertained	<u>Good and Supt.</u>
Planksheers	"	Keelsons		Sails	
Sheerstrakes	"	Clamps and Shelves		Anchors No. of	
Topsides	"	Ceiling		Cables	
Wales	"	Rudder	<u>Good</u>	Hawsers and Warps	
Plating	"	Copper	<u>Paint</u>	Standing & Running Rigging	
Plank (Bottom) and Counter	"	Caulking of	<u>When put on</u>		
Engine Room Skylights		Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunker, Openings, Lids, &c.		Scuppers		Cargo and Main Hatchways	
General Observations and Opinion.				Hatches	

It being observed that no open Ports or Scuppers are arranged for on the Main Deck, for discharge of water, a letter to the Owners was posted on the 25th Inst; informing them of the same, and asking them to take steps to comply with the Rule; No action having been taken in the matter and the Ship now ready for sea.

The Amount of Entry Fee.....£ : : is received by me, I respectfully report accordingly -
 Special..... : :
 Certificate (if required) : :
 Committee's Minute 2nd May 1873
 Character assigned Exemption Character
Noting to owner.
Letter 2/5/73

Henry J. Syrett