

Sent to Chief Surveyor

5-6-94

Received from Chief Surveyor

VESSEL'S NAME

Inv. S. S. "Mineral"

Report Inv. No. 30258

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S. S. No. 2

Before this case receives the consideration of the Committee the Surveyors should be requested to furnish a sketch showing the details of the ^{new} arrangements made in connection with the oil fuel system for the information of the Committee, and at the same time they should show what parts have been disconnected as stated. They should further state with reference to the accompanying tracing what action has been taken with reference to the fitting of No. 2 tank for carrying oil fuel as it was understood this way contemplated. The sketch should be amended ^{by the Committee} to agree with the vessel in the condition in which she now is.

M.A.

J.S.

Ltd Inv. 6.6.94

6.6.94