

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

3614
M. Q. S. 15. Aquitania

Report

No.

34050

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

First Entry

When due

1-100 A. 1. (Still)

4 Dns (SH-4 pt WS) & Shelter deck (SH. pt WS) lower and
Upper Dns (SH) in forward & after holds.

H. B. Hull LBA 141' 4" E+B 444' F 169' 5555' F.P. 2406.

S. K. 10 B.H. C. m. Lays a 16. P. B 524' on Shelter deck

Date of build 4. 14

M. W. 14
J. B. 14
C. L. 14



© 2018

Lloyd's Register
Foundation