

No. 4225.

Oil Engine for
the Bishi Tact No. 450

To await Report on
Main Engine & Installation

Asama Maru



Lloyd's Register
Foundation

D1

VESSEL'S NAME

Remarks of the CHIEF ENGINEER SURVEYOR for the consideration

(In cases which have to be submitted to the Classing Committee "the endorsement to be required and to show the cause or causes of such repairs, and also to bring out the case, so that the Classing Committee may have all the salient points presented Report, 24/5/92.)

REPAIRS TO MACHINERY AND BOILERS

The following permanent repairs have been done



© 2018

Lloyd's Register
Foundation