

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

4 Bridge Street, Sydney, N.S.W.

RECEIVED

8th January, 1957.

14 JAN 1957

Handwritten signature

Secretary,
N.

Sir,

We have for acknowledgement your classing letter of 8th December last respecting the "MANUNDA" and in reply to state that the Propeller and outside fastenings were ~~med~~ and the wear down found to be Port 3/16" Starboard and it is regretted that this was not reported at the of the survey and its also regretted that this nation was omitted from our reply to your previous ing letter of the 27th November.

Yours faithfully,

Handwritten signature
For the Surveyors.



Lloyd's Register
Foundation

NOTIFICATION

Handwritten initials (AT.)

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

4 Bridge Street, Sydney, N.S.W.

RECEIVED

8th January, 1957.

14 JAN 1957

etary,

We have for acknowledgement your classification of December last respecting the "WANGWANG" and state that the Propeller and outside fastenings and the wear down found to be Port 3/16" and it is regretted that this was not reported before the survey and it is also regretted that the letter of the 27th November.

Yours faithfully,

Handwritten signatures and stamps:
 R. J. [illegible]
 25 JAN 1957
 11 JAN 1957

ER
 CLASSIFICATION

LR-545-TB12-125



© 2018

Lloyd's Register
 Foundation