

Agnita

No 86948

It is submitted the Surveyor be  
requested to furnish the particulars  
regarding protection of fittings,  
lead of cables & situation of  
switches for the pump room  
lighting as these have been omitted  
from the Report.

Lr 4/5/31

*[Signature]*



© 2018

Lloyd's Register  
Foundation