

COPY

LOYD'S REGISTER OF SHIPPING



3815

MS ORIENTA QUEEN
 This Certificate
 Accompanies **YOKOHAMA**
REPORT No. 3815
 Dated 16-8-61
 18th August, 1961

We
 This is to Certify that ~~I~~ have

part
 surveyed the Machinery of the Twin Sc. M/V "ORIENTAL QUEEN" 11004 tons
of Panama on the 19th July, 1961 and subsequently, whilst the vessel
afloat and in drydock for alterations, advancement of machinery survey,
key boiler and tail shaft surveys

that ~~I~~ will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 in connection therewith have been carried out to ^{our}~~my~~ satisfaction; also
 We
~~I~~ will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
 (with date) on completion and notation of TS PAS(CL) 8.61 and DES 8.61 now

and that her Machinery Classification Record be continued in the Book.

Parts now examined :
 (C.S. Items only)

Aux. Machinery

Starboard Frd. Bilge Pump
 Starboard Aft. No.2 M/M S.W. Circ. Pump
 Starboard Aft Air Compressor.

J. WINN, S. TAKENAKA and self

P. F. H. Brebner

Engineer Surveyor to Lloyd's Register.
P.F.H. Brebner

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DES	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS (CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS (OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
 While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
 to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
 in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
 committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."