

2 E

Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

NAME Quata Rpt. Afr. No. 4189.

Views of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24592.)

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 6.42 ~~not~~ partly held 6.42 now

Completed, and the following repairs carried out (due to a nearly explosion):

Bedplate of two pumps broken; now repaired.

Brickwork of boilers partly renewed.

Port-screw shaft examined.

It is submitted the vessel is eligible to remain as classed, with

notation of BS 6.42 & Port-S. 9.42 as recommended.

MS partly held 10.41, now advanced.

24  
26/11/82.