

Lloyd's Register of Shipping.

FOUNDED 1760.

RE-CONSTITUTED 1834.

CERTIFICATE FOR ENGINES AND BOILERS.

No. 2958^{n.c.}

This is to Certify that the Engines and Boilers of the
Steel Twin Screw Steamer "L. S. I. (3) 3531"

4291 Tons, of S

have been Specially Surveyed by the Surveyors to this Society during construction at Lachine P. Q. Vancouver B.C. and were reported to be on the 8th November, 1945 at Esquimalt B.C. in good, efficient, and safe working condition, at a pressure of 225 lb. per square inch on the main ^{W.T.} boilers. The approved working pressure of the donkey boiler is S lb. per square inch.

The Record LMC 11,45 (Lloyd's Machinery Certificate) has been ^{FITTED FOR OIL FUEL 11/45 FLASH POINT ABOVE 100°F.} made in the Register Book, subject to Periodical Surveys as required by the Rules.

PARTICULARS OF ENGINES.

Description.	When Made.	Name and Address of Makers.	Diameter of Cylinders.	Length of Stroke.
<i>Triple Expansion</i>	<i>1945</i>	<i>Dominion Bridge Co. Ltd. Lachine P. Q.</i>	<i>18 1/2", 31", 38 1/2" + 38 1/2" (2 sets)</i>	<i>30"</i>

Witness my hand,

R. L. L. L.
Secretary.

G. J. J.
Chairman.

71, Fenchurch Street, LONDON, E.C. 25th January, 1946

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



©2018
Lloyd's Register
Foundation