

LONDON

COPY

# LLOYD'S REGISTER OF SHIPPING



/p.

NEWCASTLE-ON-TYNE, No 116968

Port  
NEWCASTLE UPON TYNE.

13th April, 1960.

This is to Certify that I have

Surveyed the Machinery of the G.T.S. "AURIS", 3269 tons gross of London,

whilst afloat and in drydock at North Shields,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also

that I will recommend that the case of this vessel be entered in the

Survey Records be made in the Supplement to the Register Book

A.B.S. (Scotch) 4.60,

and that her Machinery Classification Record be continued in the Book.

(Vessel laid up pending fabrication and fitting of redesigned diffuser plate).

**Parts now examined:**

(C.S. Items only)

- H.P. turbine.
- Ford. (No. 1) L.O. Pump.
- Ford. L.O. Cooler.
- Propeller and outside fastenings.

*R.P. Frazier*

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

|     |  |        |                                   |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

R.P. FRAZIER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society."



© 2018

Lloyd's Register Foundation