

Chief Surveyors

Received from Chief Surveyors

EL'S NAME Tw. Sc. M.S. "MANOORA" Report Gls No. 55412

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey First Entry When due ✓

✠ 100A1 "with freeboard"

3 Dks

Cell DB 378' 1124t DTsa 55' 442t FPT 126t ~~to~~ APT 97t

FK 6 EH pt. Cem. Lloyd's A & CP

B 280' F 86'



2018

Lloyd's Register  
Foundation