

10 JAN 1961

SHIPS NAME "EMPIRE BALTIC"

REPORT

Mlt.

No. 2455

GB

Outstanding Conditions of Class:

SUBJECT to indented shell plating (p & s) being specially examined and dealt with as necessary next drydocking and to the A.P. tank not being used as a tank pending repairs to A.P. tank top at fore end, not later than 11,60.

S.R.L. Appendix. (As before ~~or None~~)Nature of Present Survey: (Afloat and ~~in dry dock~~)

Part subject item repairs.

Recommendation:

SUBJECT to indented shell plating (p & s) being specially examined and dealt with as necessary next drydocking, but without other condition.

As Now. Subject
Without.

IN S.R.L. APPENDIX.

After part of vessel in way of skegs being specially examined each drydocking).

