

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S.S. 'EMPIRE CELTIC'Official No. 181539.Port of Registry LondonThis ship has been under survey at Talburyon June 8th 1956 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:-Three additional side scuttles with deadlights fitted:-1 - 9" between frames NO. 27/28 (from mid) Port side1 - 14" between frames NO. 24/25 Port side.1 - 9" between frames NO. 55/56 Starboard side.The side scuttles are of strong construction and in accordance with the Requirements and fitted at the same level as the existing side scuttles in the upper sheer plates.W. H. Allan
Surveyor to Lloyd's Register of Shipping.[Signature]
28-6-56.

[13 JUN 1956]

A copy of this Report has been placed on board.