

215
RETAIN
Received by Chief Ship Surveyor 27.12.46 Received from Chief Ship Surveyor _____
VESSEL'S NAME Seels Narragansett Rpt. Lon No. 79552

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

mfm Bot 1534

COMPLETION OF

S.S. No. 3

W. B. 291

The S.S. No. 3 partly held at

now completed, and the following repairs done (due to *men dead*) :-

Drum repairs only.

The port house pipe still requires to be renewed. This has now been examined & found efficient for the present, and the Surveyors recommend the pipe in question be renewed at the first opportunity.

It is submitted the vessel is worthy to remain as classed
of Survey 8.16 and notation of S.S. Lic No 3

Subject as above.

100 A 1.

Classing petition held

8.16 Lic

S.S. Lic No 3 - 8.16

Delivered for oil fuel 5.07 F.P. above 150 F



© 2018

Lloyd's Register
Foundation