

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Apr 10 1909 When Handed in at Local Office

Port of London

No. in Reg. Book.

Survey held at London on the Wood Iron or Steel T/S WARATAH Date, First Survey (No. of Vessel) Last Survey Apr 16 1909

28-

Master J. H. Burrows Year 1908 Month 10

TONNAGE:- Built at Glasgow

GROSS

UNDER DE

NET

By whom Surveyed Col. P. W. When 1908 Port belonging to London

Owners Blue Anchor Line Ltd

Owners' Address 10 Sand Lane Mps.

Surveyed Afloat or in Dry Dock? No Name of Dock Royal Albert

Destined Voyage Colonial

WB=Cell DB or DBa feet; uE&B feet; f feet; t tons; FPT tons; APT tons; MT feet tons.

total capacity

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

T.N.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler spaces.

CHARACTERISTICS
for Special Survey,
Date of last Survey and of
Periodical Survey.Year of
Annual Survey
Completed date of 2nd, 1908

Last Report, No. 27140 Port Gls

(Periodical Survey, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and

also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

~~Condition~~~~On dock:— Vessel placed in dry dock bottom~~~~Cleaned Examined and reported.~~~~Wood decks Planed in places where required~~

RETAIN

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Framing.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Removed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Boiling Plates under Scouring Pipes	Copper, or T.M. or Wood Vessels (State on Well.)
Decks	fair	ditto	Year
Caulking of Decks	fair	ditto	Month
Watervays	fair	ditto	Year
Coamings	fair	ditto	Month
Beams & Fastenings	fair	ditto	Year
Outside Plating	fair	ditto	Month
Caulking of ditto	fair	ditto	Year
Rivets	fair	ditto	Month
Breasthooks & Crutches	fair	ditto	Year
Transoms	fair	ditto	Month
Frames	fair	ditto	Year
Reverse Frames	fair	ditto	Month
Floors	fair	ditto	Year
Kellocks	fair	ditto	Month
Stringers	fair	ditto	Year
Inner Bottom Plating	fair	ditto	Month
State if Tanks have been examined inside			
State if Tanks now tested			
Bulkheads	fair	ditto	Year
Ceiling	fair	ditto	Month
Cement or Asbestos (State which)	fair	ditto	Year
Rudder	fair	ditto	Month
Steering gear and its connections	fair	ditto	Year
Windlass	fair	ditto	Month
Have Pumps now been examined and found efficient?			
Have Valves now been examined and found efficient?			
Have Watertight Doors now been examined and found efficient?			
Boats	fair	ditto	Year
Masts, Yards, &c.	fair	ditto	Month
Condition, how ascertainable (State if judges concerned)			
Cargo Hatchways	fair	ditto	Year
Hatches	fair	ditto	Month
Planking of Wood Vessels	fair	ditto	Year
Caulking	fair	ditto	Month
Treenails	fair	ditto	Year
Breasthooks & Stemson	fair	ditto	Month
Transoms, Pointers, & Crutches	fair	ditto	Year
Timbers of Frame at openings	fair	ditto	Month
Ditto ditto at other places	fair	ditto	Year
Stringers, Clamps & Shelves	fair	ditto	Month
Salting	fair	ditto	Year
(State if examined)			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed and to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1/07, or "to remain as classed and to have record of survey, 1/07, and the notations of No. 1-07 and PTND07, &c."

This vessel is in my opinion Eligible to remain as classed, and to have record of survey at 1/07

Survey Fee (per Section 28)	£	Fee applied for
Special Damage or Repair Fee (if any)	£	10
Travelling Expenses (if chargeable)	£	Received by me
Second Surveyor's Fee (if any)	£	10

Committee's Minute

Character Assigned

FRI. 7 MAY 1909

George J. Hobson

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2018

Lloyd's Register
Foundation