

## LLOYD'S REGISTER OF SHIPPING

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "IONIAN" ex "Ionia", LR 516243. Official No. 1091.

Port of Registry PANAMA.

This ship has been under survey at Hong Kong,

on 10th June, 1965, ~~-195-~~ and the following alterations to the conditions of  
assignment of loadlines have now been effected/~~found~~:-

Shell Gangway Doors :-

Four shell gangway doors refitted at this time between upper and second deck as  
detailed hereafter :-

1 - Cargo Door P. &amp; S. at frames 124 - 126.

1 - Cargo Door P. &amp; S. at frames 50 - 52.

Clear opening 5'-0" x 2'-6" with hinged steel door .50" thick reinforced  
by 2" x .50" stiffener and secured watertight by 3 @ 4" x 3" x .50"  
fabricated channel strongbacks.

*James I. Mathewson*  
James I. Mathewson

Surveyor to Lloyd's Register.

HONG KONG.

10th June, 1965.

*Noted*  
*26/7/65*

A copy of this Report has been placed on board.