

1
Recd. to Chief Surveyors 28.6.37

Received from Chief Surveyors

VESSEL'S NAME

SA Le CEDROS'

Report

L.A.

No. 2694

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Condition

When due

Subject to bottom plating being jaired at the Owners convenience.

MAB

Lof.

29.6.37.

~~4-7~~

8+2

Electrically Welded



© 2018

Lloyd's Register
Foundation