

A.B. Atlas Diehl

Engineer Nos. 85-5-03-05-

Phm. 4441.

It is submitted that before this case
receives consideration the lawyers be requested
to furnish the size of the crank webs, as
this has been omitted from the report.

2nd 19/6

002024-002037-0177

Lloyd's Register
Foundation

Mr. Stephenson



© 2020

Lloyd's Register
Foundation