

Nos 1071-72 & 73 & 1087 & 1088
140.Ö.B.P. * 25.Ö.Ex. * 14.3.MLD.

2-9-30



BUTTS OF SHELL PLATING TO BE LAPPED
AND DOUBLE RIVETTED EXCEPT GARBOARD,
SHEERSTRAKE AND E AND F STRAKES IN
WAY OF CHAFING BARS, WHICH ARE TO BE
STRAPPED AND DOUBLE RIVETTED
ALL LANDINGS DOUBLE RIVETTED
BULWARKS SINGLE RIVETTED

No. 1087

Mid Ship Section - (as built)

Cochrane & Sons Rs.

S.S. "Cordela"

HULL REPORT No. 41216.



© 2020

Lloyd's Register
Foundation

002051-002061-0161