

Do. of e.
Do. abov
Engin
Gross 1

HN Hofdaborg

4 Plans

1m.12.15.

F.E.

Received by Chief Ship Surveyor 17.3.16 ^{ex}

Received from Chief Ship Surveyor

VESSEL'S NAME Sheers "Belgaum"

Rpt. 1st

No. 29190

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 37.83

Depth "d" 12.5

Framing: Table No. 3 page 10 Description Single Angle as approved.

Longitudinal No. 5296.

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.12}{}$

BEVL
Do. in
VU
V

~~Deck~~ Sheerstrake .56 of an inch instead of .38 as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A-1. (Steel) "Steam Trawler" as recommended.

* 100A-1. (Steel) "Steam Trawler"

15K.

BK 7/2. 4 BH. Cam. Lloyd's reg. 076 F21



17.3.16
© 2020

Lloyd's Register
Foundation

002062-002070-0070

BEAM
" "
BEAM