

BOARD REPORT on the

S/S. Fairmair


Slb 34757

It is submitted the Surveyor be requested to state the height of the deck erections omitted from his report. also to explain why an addition of 9 tons has been made to the under deck tonnage on account of peak tanks as it is understood that these spaces would be included already in the under deck tonnage measurement.

Am 25/1/15

GRM

ACD
25 Jan 1815



© 2020

Lloyd's Register
Foundation

002062-002070-0137