



Lloyd's Register of Shipping.

(Report on Vessel No. 40517 Port Hull)

No.

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by L. S. Foster & Son Ltd of Sunderland for the Vessel No. 1066, being built by Cochrane & Son Ltd of Selly have been inspected by me as set forth below and found to be, so far as can be seen, Sound.



on Forgings or Castings.

Lloyd's

No. 54478-10-29D. D. WilliamsonSunderland, 8-10-29

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...		<u>Scrap Iron</u>	
made ...		<u>Forged</u>	
healed ...			
sions ...		<u>5" dia 5" x 4" to 3 1/4" x 3"</u>	
ess on Inspection ...		<u>Forged & Finished</u>	
when Inspected ...		<u>3-9-29 to 8-10-29</u>	
CASTINGS.			
on Standard Test Pieces.			
e Test—			
us per square inch ...			
ension per cent. ...			
tending Test—			
le before fracture			
Test—			
ght from ground ...			
ering Test—			
ade according to Rules			
nd found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



be (if any chargeable) £

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.