

Im.7.41.

The Lytham Shipbuilding & Engineering Co. Ltd.,  
Lytham.

Yard No. 865.

1

This is a sister vessel to the "MAPLEFIELD"

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME LARCHFIELD

REPORT

Liv

No. 116839

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY

When due

100A1

1 Dk

DTf 11' 71t, FPT 30t, APT 37t

BK6½", 4BH, Cem., Lloyd's A & CP

P49' Q36' F21'

Mchy Aft

O.L. 148.3'

g

The Certificate of Classification to be endorsed "Cargo ballens not fitted" and the same notation to be printed in the Register Book.

*[Handwritten signature]*

*J.C.D.*  
8/11.41



© 2020

Lloyd's Register  
Foundation

002157-002164-0181