

Built at Selly By whom built Cochrane & Sons Ltd

Yard No. 1064

No. 1379

No. 1379

Port belonging to

Is Electr

For the information of Surveyors and the Committee only.

Received at _____ Office 24 SEP 1929

Lloyd's Register of Shipping.

(Report on Vessel No. 40461 Port Aull)

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Y. S. Forster & Sons Ltd Sunderland for the Vessel No. 1064, being built Cochrane & Sons Ltd of Selly have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

Forgings or Castings.

Lloyd's
No. 5377
23-9-29

D. D. Williamson


Sunderland, 23-9-29

	STERN FRAME.	RUDDER FRAME.	STEM.
...	/	Scrap Iron	/
...		Forged	
...		<u>5 1/2 dia 5 1/2 x 5 1/2 x 3"</u>	
...		Finished	
...		<u>23-9-29</u>	
Inspection ...			
Inspected			
STANDARDS.			
Standard Test			
pieces.			
Test—			
square inch			
per cent. ...			
ing Test—			
ore fracture			
ground ...			
Test—			
according to Rules			
and satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £ : :
to be paid at _____

on, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



Revs
No. of Cra
Thickness
shrunk
Thickness
per Rule 7.1
fitted 7/2
with a continuo
the after end of th
thickness of the lin
in water and no
Gland or othe
eller 36
Total Develop
hailed while the
hailed while the
and size
ected to both Ma
Direct Suctio
res Yes
straight tail
Both
yes above or belo
th a spigot and
ord
into the cargo
wo
Sg. f
Working
rded?
Arrangemen
both
raw
shaft