

SHIPS NAME

"LUTANA"

REPORT

Mel.

No.

13896

26 SEP

Outstanding Conditions of Class:

Subject to indented bottom shell plating frames 11-17 'A' strake (s.s.) and frames 18-49 'B' strake (s.s.) being dealt with next Special Survey.

Endorsement of Class (B) (As before ~~original~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to fractured port hawsepipe.


Recommendation:

SUBJECT as above, also to port hawsepipe being renewed at the next Special Survey.

As Now. Subject.

ENDORSEMENT OF CLASS(B).

Indents in shell plates(p.s.f.)
Rudder mainpiece slightly twisted.



© 2020

Lloyd's Register
Foundation

002174-002183-0192

Handwritten signature and date:
21.9.51